

## DA08-NA/E, DA10-NA/E

### Programming instruction for digital panelmeters with analogue inputs (Version 08/2002)

#### All Keys are on top of the case

- Key T1: carries out the adjustment of the selected digit  
 Key T2: selects the programming digit (is shown by the luminous decimal point). The final value of display is assigned to the **MP 2 + 4** by using of key after the minimal and maximal input signal.  
 Key T3: changes from normal-mode into programming-mode.

#### MP Display Function / Description

<b>Pr</b>	<b>---</b> <u>0</u>	<b>Calibration</b> 0 = calibration <b>external</b> with external measure signal A = calibration <b>internal currency</b> (-19mA ... +20mA DC) without external measure signal U = calibration <b>internal voltage</b> (-10V ... +10V DC) without external measure signal
<b>P0</b>	<b>----</b>	<b>Adjustment of the minimal value of display</b> The value can be positive or negative
<b>P1</b>	<b>P-L</b>	<b>Take-over of the minimal input signal to be applied</b> <b>External calibration:</b> The minimal input signal must be connected on the measure input <b>Internal calibration:</b> Select the minimal input value with T1 and T2. Press the key T3 and the minimal value of display adjusted under <b>P0</b> will be assigned to the minimal input signal. The display indicates « <b>P-L</b> ».
<b>P2</b>	<b>----</b>	<b>Adjustment of the maximal value of display</b> If you need a decimal point, you have to place it on the right position before leaving this menu-point.
<b>P3</b>	<b>P-H</b>	<b>Take-over of the maximal input signal to be applied</b> <b>External calibration:</b> The maximal input signal must be connected on the measure input <b>Internal calibration:</b> Select the maximal input value with T1 and T2. Press the key T3 and the maximal value of display adjusted under <b>P2</b> will be assigned to the maximal input signal. The display indicates « <b>P-H</b> ».
<b>P4</b>	<b>---</b> <u>0</u> <b>1</b>  <b>-</b> <u>L</u> <b>-</b>	<b>Adjustment of the average value</b> Possibilities: <b>1 - 99</b> measurements. The adjusted value will be shown on the display. <b>Line break indicator</b> Possibilities: <b>_</b> = no, <b>L</b> = yes (only by measuring 4-20 mA). If value falling below 25% of measuring value (< 3 mA ) the display indicates « <b>- L-</b> ».
<b>P5</b>	<b>---</b> <u>0</u>	<b>Roundness of the last digit</b> This value effects only at the display. Possibilities: <b>0</b> = without roundness, or with roundness by steps of 2 ( <b>2</b> ), 5 ( <b>5</b> ), or 10 ( <b>10</b> ).



**Option: " F " (Input function):**

**MP Display Function**

---

P6	Display	Function input
	---	Without input function
	---0	0 = Function Input off
	---1	1 = Display dark (all segments off)
		2 = Segmenttest (all segments on)
		3 = Display hold (Display hold the last value)
		4 = displayed <b>ON</b>
		5 = displayed <b>OFF</b>
		6 = displayed <b>HELP</b>

---

After operating of T3 the display changes back into standard-mode

For a period of about 3 seconds the message « **EE** » appears on the display.  
The adjusted values are stored into the EEPROM during this time.